TES4-T10-3513-02- G2-09-00(

515 South Flower Street Los Angeles, California 90071 Telephone 213 486 1713 1/5/88

5.1

Roseann C. Stevenson Manager Superfund Policy and Multiparty Sites

January 5, 1988

L

Ms. Lori Cohen
U.S. Environmental Protection Agency
Superfund Branch HW-113
1200 6th Avenue
Seattle, WA 98101

JAN 05 1988

Dear Ms. Cohen,

Superfund Branch

RE: Harbor Island Superfund Site

Pursuant to your request for additional information, ARCO Petroleum Products Company has attached our response. We apologize for the delay in this response, however, the environmental assessment report for the work performed in July was just received. This report included the boring and well logs which were requested.

Should you have any questions or require additional information, please contact me at 213/486-1713.

Sincerely,

R. C. Stevenson

ATTACHMENT

cc: J.A. Miller

J.P. Meck

1163399

441330

ARCO Petroleum Products Company, on behalf of Atlantic Richfield Company, objects to all of the information requested since it is not limited to hazardous wastes as defined by applicable federal and state statutes and regulations. To the extent that it is not so limited, it is beyond the scope of both RCRA and CERCLA, as amended. Without waiving this objection ARCO responds as follows.

- 1. Yes, ARCO regular gasoline which contains lead is stored on site. The attached Material Data Sheet indicates that lead alkyls are contained.
- No, lead is added at the refinery.
- 3. Current practice is to determine if the material is hazardous pursuant to state regulations and properly transport and dispose of the material. Our files on tank cleanings prior to the promulgation of hazardous waste regulations do not indicate the final disposition of this material. General industry practice during this time was to spread the material and allow aeration to, if appropriate, mitigate any hazard posed by the material.

Our records indicate that a firm by the name of Haworth & Son, currently identified as Ryan & Haworth, 20519 60th Ave. W., Lynwood WA, performed all tank cleaning.

- 4. No, any lead is currently added at the refinery. Past practice may have been to add the lead at the facility, however, we have not been able to determine if this practice was utilized and, if so, when this practice may have been discontinued.
- 5. Yes there are two (2) oil/water separators at this facility. Both are permitted with one discharge to the river and the other to the metro sewer system. Sand/sediment from these separators are evaluated for hazardous characteristics pursuant to state law and are then properly transported and disposed of. Past practice and current practice if the material is not deemed to be regulated, is to spread the material onsite.
- 6. Yes, the material is a protein foam. No sludge has been generated from the foam tank.
- 7. Yes, Shell Sol which is a mixture of mineral spirits and petroleum solvents and Chevron Thinner 325 which is a mixture of petroleum solvents. MSDS's for these chemicals are attached.
- 8. Storage is in drums. Shell Sol has a usage rate of 75 gpy and Chevron Thinner has a usage rate of 220 gpy.
- 9. No leak detection systems are in place. Leak detection is by both visual and volume checks.
- 10. The information on spill history at this facility is attached.
- 11. The information on underground tanks is attached. Monitoring is by volume, no leak detection in place.

- 12. An oily sheen has been noticed when the tide goes out along the shoreline of the facility. A well was completed to monitor this occurence. This well is apparently still in place. No information on the well is available.
- 13. No information is available for this request. Should the information become available, it will be forwarded to you. At this time, we believe that these wells are still in place.
- 14. See answer to 13 above.
- 15. Yes, there are currently three (3) recovery wells in operation at the facility. ARCO performed an environmental assessment to evaluate the sheen reported in 12 above. This assessment included a comprehensive boring and drilling operation at the facility. All boring and well logs are attached. All borings were grouted in. All monitoring wells are in place.

The reason that this program was commenced was that no information on the previously drilled wells, including logs and specifications was available.

- 16. We believe that this information was previously submitted. If not, we will supply it if necessary.
- 17 & 20 Clean Sound has an office on this property and performs cleanups of spills and other incidents on the river. An underground heating oil tank is located on this property.

Stevedoring Services of America uses this area for the storage of steel used in building construction.

Seattle Freight uses this area for their mobile office and stores tractor/trailers on the property. Minor repairs of vehicles is apparently performed.

- 18. No, no gasoline filters are used.
- 19. A map of the facility with the location of tankage as well as the boring and well locations is attached. The tanks have been painted in the past, however, no information on the sandblasting material and its final disposition is available. No information on whether the paint contained lead is available.

3/86

Received at Facility 4-07-84

Sect	lon I	
1.	Escillor 10A723 Technical Review I	Date 4-07-86 Reviewer D Cherry &
,	MSDS No. F-PS 50 7 Supplies	MSDS Date 10/82
2.	,	
3.	Material Name SHELL SOLLINE	MA SPIRAS (SOLVENT)
4.	Manufacturer Name SHELL CANADA	LIMITED TORONTO ONTAKIO
5.		O.D. SNIDER, SUMNER, WA.
Sec	tion II - Primary APPCo Review	Response*
1.	Does Supplier state material is an HCR Hazardous Chemical?	YN_X_U
	In absence of supplier statement, do you material a HCR Hazardous Chemical? If yes, explain your decision basis-	Constitution 17 minimum of constitution
	flammable - health Effe	uts
 3. 	Does the MSDS adequately identify haza protective equipment and safe handling plf not, explain. Assign Labeling Categories (per Labeling	practices:
	DANGER	HEALTH / from
	WARNING	FIRE 2 msds
	CAUTION	REACTIVITY 0
		OTHER
		, 0-No Significant Hazard, Other (See NFPA)
Se	ection III - Review for Local Use	
1.	Do you recommend the intended use of in your facility?	this product YNU
	List any special conditions or restriction to your acceptance.	ns
2.	Management Approval of Use(If needed)	Date
U	Y = Yes, N = No, U = Uncertain. Ipon completion forward one copy with the I AP 3320.	MSDS to APPCo Central MSDS File at E&H

warehouse somen,

NOTED

FEB 25 1986

Shell Canada Code

642-100



INDUSTRIAL HYGIENE
OUT 1 2 1982
SHELL
MATERIA

SHELL CANADA LIMITED

MATERIA: SAFETY DATA SHEET

Hazard Rating (NFPA-704M)



Information on this form is furnished to the requesting party as a customer service and is not to be used for any other purpose, reproduced or published. While the information is based on data drawn from sources considered to be reliable. Shell Canada Limited does not guarantee the accuracy of the Information and any express or implied warranty with respect thereto or the results obtained from the use thereof is expressly excluded.

	S	ECTION I			
MANUFACTURES NAME	SHELL CANADA LIMITED		an control and the control of the co		EMERGENCY TELEPHONE NO. SHELL: 416-597-7042 (bs. hrs.)
ADDRESS P.O. BOX	400, TERMINAL A, TORONTO,	ONTARIO,	M5W	1E1	POISON CONTROL CENTRES 416-597-1500 (24 hrs.) 418-656-8000 (24 hrs.)
CHEMICAL NAME AND SYN	NONYMS PIRITS/PETROLEUM SOLVENT			TEARE	CAMSOL MINERAL SPIRITS
CHEMICAL FAMILY	YDROCARBON	FORMULA			

	SECTION II HAZARDOUS INGREDIENTS*								
COMPOSITION	%	SPECIES	LDFOL	ma/ka	LC50	ma/m-			
CONTROL CONTROL	-		ORAL	DERMAL	CONCENTRATION	HOURS			
Hydrocarbon Analysis									
o Saturates (% vol.)	89-94	+				4			
o Aromatics (% vol.)	6-15	RAT 1	> 8000	> 4000	> 14100	4 .			
o Sulphur (% by mass)	.1 mas								
			d.e.						
BENZENE CONTENT									
PAH CONTENT									

REFERENCES + Oaraffins and Naphthenes

1. Shell Data

SECTION III PHYSICAL DATA								
BOILING POINT °F(°C) 320-400	(160-204)	SPECIFIC GRAVITY (H20=1) © 60°F (15.6°C)	.787798					
VAPOR PRESSURE (mmHg) @ 100°F (38°C)	7.0	PERCENT VOLATILE BY VOLUME (%)	100					
VAPOR DENSITY (AIR = 1)	4.8	EVAPORATION RATE INBUAC = 11	.1					
SOLUBILITY IN WATER	INSOL.	VISCOSITY						
APPEARANCE AND ODOR Light colour, clear, liquid,	hydrocarbon	AUTOIGNITION TEMP °F(°C)						

PLOSION HAZARD DATA		
FLAMMABLE LIMITS % VOL. IN AIR	Lel L.U	D • O
y chemicals (preferr	ed)	
	FLAMMABLE LIMITS % VOL. IN AIR	FLAMMABLE LIMITS Lei

Exclude air; do not use water except as a fog. Handle as a flammable liquid. Wear adequate respiratory protection.

UNUSUAL FIRE AND EXPLOSION HAZARDS

Vapour forms an explosive mixture between upper and lower flammable limits.

SECTION V HEALTH HAZARD DATA

SHELL SOL

OLD LIMIT VALUE Suggested TLV 100 ppm (525 mg/m³) value for Stoddard Solvent ACGIH 1980. THRESHOLD LIMIT VALUE ECTS OF OVEREXPOSURE Moderately irritating to skin and eyes; repeated or prolonged

contact can cause dermatitis.

SKIN AND EYES:

INHALATION:

The vapours are moderately irritating to the eyes and respiratory passages. Prolonged exposure to high vapour concentration can

INGESTION:

cause headaches, nausea, dizziness, anesthesia and central nervous

system depression and in rare cases may sensitize heart muscles

CARCINOGENIC HAZARD: causing heart arrythmia.

EMERGENCY AND FIRST AID PROCEDURES

WHALATION:

SKIN AND EYES:

STABLE X

SACOMPATIBLE MATERIALS

Remove victim to fresh air and restore breathing if required. Wash contaminated skin with mild soap and water. Flush eyes with water for at least 15 minutes. Wash contaminated clothing before

ENGESTION:

reuse. DO NOT INDUCE VOMITING. GET MEDICAL HELP IMMEDIATELY.

SECTION VI REACTIVITY DATA CONDITIONS TO AVOID Avoid spark, open flames and all other sources of ignition. Avoid strong oxidizing materials HAZARDOUS DECOMPOSITION PRODUCTS CO, CO, produced on combustion

CONDITIONS TO AVOID HAZARDOUS POLYMERIZATION YES NO X

UNSTABLE

SECTION VII SPILL OR LEAK PROCEDURES

S TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Eliminate all sources of ignition. Flush with water to an open, well-ventilated area. Wear adequate respiratory protection. Absorb with absorbent material. Remove to a contdiner. KEEP MATERIAL AWAY FROM SEWERS AND WATERWAYS.

WASTE DISPOSAL METHOD

Dispose of by controlled (approved incinerator) burning or landfill the absorbed material in an (Government) approxed site.

SECTION VIII SPECIAL PROTECTION INFORMATION RESPIRATORY PROTECTION (Specify type) . Approved organic canister mask or air supplied respirator. LOCAL EXHAUST Desirable VENTILATION MECHANICAL (General) To maintain suggested TLV; electrical & mechanical equipment should be PROTECTIVE GLOVES EYE PROTECTION Impervious Rubber Gloves Chemical safety goggles to guard OTHER Overalls, Apron against splashing.

SECTION IX SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING, STORAGE AND USE:

Store in cool, well-ventilated area. Avoid all sources of ignition. Avoid excessive heat. Avoid prolonged or repeated contact with skin. Avoid breathing vapours. Use normal, good, personal hygiene.

CANADALIMITED

Ontohar

Shell Canada Limited assumes no responsibility for injury to vendee or third persons proximately caused by the material if reasonable safety procedures are not adhered to as stipulated in the data sheet. Additionally Shell Canada Limited, assumes no responsibility for injury to vendee or third persons proximately caused by abnormal use of the material even if reasonable safety procedures are followed. Futhermore, vendee assumes the risk in his use of the material.

. Figar Customer: This MSDS contains important environmental, health and texicology information for your employees who recently ordered this product. Please make sure this information is given to them. If you result this product, this MISDS should be (Iven to the Buyer. This form may be reproduced without permission.

Material Safety

Prepared According to the OSHA Hazard Communication Standard (29 CFR 1910.1200). (Formerly Called MATERIAL INFORMATION BULLETIN)



CHEVRON Thinner 325

CPS 218223

DANGER!

HARMFUL OR FATAL IF SWALLOWED

COMBUSTIBLE

KEEP OUT OF REACH OF CHILDREN

TYPICAL COMPOSITION

Light petroleum distillate (CAS 64742-47-8) containing:

Paraffins and naphthenes

Aromatics:

C9-C11 alkylbenzenes (CAS 68515-25-3)

similar

Benzene (CAS 71-43-2)

988

28 <.02%

EXPOSURE STANDARD

No Federal OSHA exposure standard or ACGIH TLV has been established for this material. Based on information reviewed to date, we recommend an exposure standard of 100 ppm for a daily 8-hour exposure.

PHYSIOLOGICAL & HEALTH EFFECTS

EMERGENCY & FIRST AID PROCEDURES

Eyes

Flush eyes immediately with fresh water for at least 15 minutes while holding the eyelids open. If irritation persists, a doctor.

material into the eyes of rabbits produced slight membrane irritation without corneal

irritation. Application of a

injury.

Not a primary skin irritant but may cause skin irritation on prolonged or frequently repeated contact. Application of a similar material onto the skin of rabbits produced moderate erythema and edema. The Draize score was 3.7. See Additional Health Data.

Expected to cause no more than minor eye

Wash skin thoroughly with soap and water. See a doctor if irritation occurs. Launder contaminated clothing.

Inhalation

Expected to have slight acute toxicity by inhalation. The inhalation LC50 (rat) of a similar product for a one-hour exposure was greater than 13.3 mg/liter. Breathing the vapors at concentrations above the recommended exposure standard can cause central nervous system effects. Additional Health Data.

If there are signs or symptoms, described in this MSDS, due to breathing this material, move person to fresh air. If breathing has stopped, apply artificial respiration. Call a doctor immediately.

Ingestion

Not expected to be acutely toxic ingestion. The acute oral LD50 (rat) for a similar product was greater than 15.3 g/kg. Note to Physician: Ingestion of this product or subsequent vomiting can result in aspiration of light hydrocarbon liquid which can cause pneumonitis.

If swallowed, give water or milk to drink and telephone for medical advice. DO NOT make person vomit unless directed to do so by medical personnel. If medical advice cannot be obtained, then take the person and product container to the nearest medical emergency treatment center hospital.

Chevron Environmental Health Center, Inc., P.O. Box 4054, Richmond, CA 94804-0054 Emergency Phone Number (415) 233-3737

X-IRC021 (07-85)

No. 47

ADDITIONAL HEALTH DATA See following pages

SPECIAL PROTECTIVE INFORMATION

Eve Protection: Do not get in eyes. contact can be avoided by wearing chemical safety goggles.

Skin Protection: Avoid prolonged frequently repeated skin contact with material. Skin contact can be minimized by wearing impervious protective including rubber gloves.

Respiratory Protection: Wear approved respiratory protection such as an organic vapor cartridge respirator or an airsupplying respirator unless ventilation equipment is adequate to keep airborne concentrations below the recommended exposure standard.

Ventilation: Use adequate ventilation to keep airborne concentrations this material below the recommended exposure standard.

FIRE PROTECTION

Liquid evaporates and forms vapors (fumes) which can catch fire and burn violence. Invisible vapor spreads easily and can be set on fire by many sources such as pilot lights, welding equipment, and electrical motors switches. Fire hazard is greater as liquid temperature rises above 85°F.

Flash Point: (TCC)105°F(41°C) Min. Autoignition Temp.: 500°F (260°C) Plammability Limits: 1.0-6.0%

Extinguishing Media: CO2, Dry Chemical,

Foam, Water Fog.

Special Fire Fighting Procedures: fires involving this material, do not enter any enclosed or confined fire spaces without proper protective equipment. This self-contained include breathing apparatus to protect against the hazardous effects of normal products of combustion or oxygen deficiency. Read the entire MSDS.

SPECIAL PRECAUTIONS See following pages ENVIRONMENTAL PROTECTION Environmental Impact: Certain geographical areas have air pollution restrictions concerning the use of materials in work situatuions which may release volatile components to the atmosphere. pollution regulations should be studied to determine if this material is regulated in the area where it is to be used.

Precautions if Material is Released or Spilled: Eliminate all open flame vicinity of spill or released vapor. Stop the source of the leak or release. Clean up releases as soon as possible, observing precautions in Special Protective Information. Contain liquid to prevent further contamination of soil, surface water or groundwater. Clean up spills using appropriate techniques such as sorbent materials or pumping. feasible and appropriate, contaminated soil. Follow prescribed procedures for reporting and responding to larger releases.

Waste Disposal Methods: Place contaminated materials in disposable containers and dispose of in a manner consistent with applicable regulations. Contact environmental or health authorities for approved disposal of this material.

REACTIVITY DATA

Stability (Thermal, Light, etc.): Stable. Incompatibility (Materials to Avoid): May react with strong oxidizing materials. Hazardous Decomposition Products: Normal combustion forms carbon dioxide and water vapor; incomplete combustion can produce carbon monoxide.

Hazardous Polymerization: Will not occur.

PHYSICAL PROPERTIES

Solubility: Miscible with hydrocarbons; insoluble in water.

Appearance (Color, Odor, etc.): Colorless liquid.

Boiling Point: 166°C (330°F) 5% Rec. (Max.)

Melting Point: n/a

Specific Gravity: 0.78 @ 15.6/15.6°C Vapor Pressure: 5 mm Hg @ 77°F Vapor Density (Air=1): 4.8 Percent Volatile (Volume %): 99+ Evaporation: (Bu Ac=1) 0.22 Viscosity: 0.96 cSt @ 37.8°C

n/a = Not Applicable

The above information is based on data of which we are aware and is believed to be correct as of the date hereof. Since the information contained herein may be applied under conditions beyond our control and with which we may be unfamiliar and since data made available subsequent to the date hereof may suggest modifications of the information, we do not assume any responsibility for the results of its use. This information is furnished upon the condition that the person receiving it shall make his own determination of the suitability of the material for his particular purpose.

Material Safety Data Sheet

CHEVRON Thinner 325

CPS 218223

ADDITIONAL HEALTH DATA

Not expected to be acutely toxic by skin contact; the acute dermal LD_{50} (rabbit) for a similar product was greater than 19.1 g/kg.

Signs and symptoms of central nervous system effects may include one or more of the following: headache, dizziness, loss of appetite, weakness and loss of coordination. Affected persons usually experience complete recovery when removed from exposure area.

SPECIAL PRECAUTIONS

READ AND OBSERVE ALL PRECAUTIONS ON PRODUCT LABEL.

DO NOT USE OR STORE near flame, sparks, or hot surfaces. USE ONLY IN WELL VENTILATED AREA. Keep container closed.

DO NOT weld, heat or drill container. Replace cap or bung. Emptied container still contains hazardous or explosive vapor or liquid.

CAUTION! Do not use pressure to empty drum or explosion may result.

HMIS Hazard Rating:

Reactivity: 0, Flammability: 2, Health: 1

Spill History of the ARCO Seattle Petroleum Products Terminal

MAY 10 1987

Alaka ta Mar

Corrected Copy

February 6, 1987

2,000 galllons of regular leaded gasoline were released from a roof drain failure in tank number one. The released product floated on top of water in the tank dike and was fully recovered using a vacuum truck.

December 19, 1979

15 to 20 gallons of diesel were released when the oil/water separator overflowed due to heavy rains. This product was completely recovered using a vacuum truck.

June 8, 1979

8,473 gallons of regular leaded gasoline were released when tank number nine was overfilled. The product was not recovered at the request of the USCG and the fire department (due to their concern for the fire hazards involved).

1968 through 1972

We know that there was a black oil spill when tank number eleven over flowed sometime during the above stated four year period. We do not know the exact date, the amount or if any of the product was recovered.


DATE: 8/28/87

SEATTLE

UNDER GROUND TANKS


TANK	SIZE	AGE	LAST TEST
1. T & T Rack Drop Out Tank	(b) (4) _{gal}	9 + yrs	6/27/84
2. Vapor Recover Drop Out Tank	gal	7 yrs	7/23/84
3. Sample/Bleeder for Pipeline Receipts	gal	7 yrs	6/22/84
4. Slop Oil Tank Warehouse	gal	7 yrs	6/08/84
5.*Heating Oil Tank Clean Sound		24 + yrs	6/11/84
6. Garage Waste Oil Tank	(b) (4) _{gal}	24 + yrs	6/11/84
7. O/W Separator Tank Plant #2	gal	5 yrs	6/12/84

^{*} This tank will be removed when empty by Clean Sound. (Spring of 88)



APPENDIX A

SO!L BORINGS AND MONITORING WELL LOGS



1 Sec.

SOIL MOISTURE TERMINOLOGY

Moisture Characteristic Slightly Moist Moist Very Moist Wet

Makes dust Below plastic limit At plastic limit Above plastic limit -can pump water from silts Free water or saturated

TERMS DESCRIBING COMPACTNESS OF COARSE-GRAINED SOILS

	Corrected SP	T
Compact::ess	Penetration (blows/foot)	Relative Density
Very Loose	0 to 4	0 to 15%
Loose	4 to 10	15 to 40Z
Medium Dense	10 to 30	40 to 70%
Dense	30 to 50	70 to 85%
Very Dense	+50	85 to 1007

TERMS DESCRIBING CONSISTENCY OF FINE-GRAINED SOILS

Consistency Very Soft	SPT Penetration (blows/foot)	(
	2	0.25
Soft	2 to 4	0.25 to 0.50
Medium	4 to S	0.50 to 1.00
Stiff	8 to 15	1.00 to 2.00
Very Stiff	15 to 30	2.00 to 4.00
Hard	30	4.00

SIZE PROPORTIONS

Designation	Percent by Weight
Trace	0 to 10
Little	10 to 20
Some	20 to 25
And	25 co 50

SOIL SAMPLE TYPES


- STANDARD SPLIT SPOON
- CALIFORNIA SPLIT SPOON (MODIFIED)
- GRAB SAMPLE
- HAND AUCER

UNIFIED SOIL CLASSIFICATION SYSTEM

GRAPH LETTER

A	AJOR DIV	ISIONS	SYMBOL	SYMBOL	TYPICAL DESCRIPTIONS		
	GRAVEL	CLEAN GRAVELS		GW	#[[[-6480[8		
COARSE GRAINED	SOILS	FINES!	•	GP	PODRLY-CRISCS CRIPTLE, CRIPTLE SIND WISTURCS, LITTLE OF NO FINES		
SOILS		GRAVELS WITH FINES	•	GM	SILT CRAVELS, CPAVEL-SAME.		
***	710M #C741MCQ	97 ***(\$1		GC	CLATE SPANCES, SHANCE-SAMB. CLAT MITTURES		
Substitute of the substitute o	SANO	CLEAN SAND	o 0 a	sw	SANDS, LITTLE OR NO FINES		
WORE THAN 30 % OF WATERING IS	SANDY SOILS .	FINES ,		SP	PODRLT-6*4000 SANOS, GRAVELLY SANOS, LITTLE 0* NO FINES		
200 31EVE 31EE	OF COAMSE FRAC.			s м	SILT SANDS, SAND-SILT MISTURES		
	1104 <u>PASSING</u> NO 4 SIEVE	of fines)	0.0	sc	CLATET SANOS, SANO-CLAT MISTURES		
				ML	INDREAMIC SILTS AND VERT FINE SANDS, ROCK FLOWN, SILTY OR CLAFET FINE SANDS OR CLAFET SILTS WITH SLIGHT PLASTICITY		
FINE GRAINED SOILS	AND CLAYS	LESS T-+- 50		CL	PASSIBLE CLASS OF LOW TO MCDIMM PASSIBLET, ERRYELLY CLASS, SAMP CLASS, SILTY CLASS, LEAR CLASS		
				OL	ORCANIC SILTS AND ORCANIC SILTY CLAYS OF LOW PLASFICITY		
				мн	INDRESHIC SILTS, WICACCOUS OR BISTOWICCOUS FINE SAND OR SILTY SOILS		
OF MATERIAL IS WALLED THE HO 200 SIEVE SIZE	SILTS AND CLAYS	\$25-752 Tree 30		СН	PLASTICATE, PAT CLAYS		
				он .	OPERMIC CLATE OF MEDIUM TO MEN PLASTICTY, ORGANIC SILTS		
нісн	LY ORGANIC SC	DILS		PT	PERT, HUMUS, SWEAP SOILS WITH MICH GREANIC CONTENTS		

USCS ,RAIN-SIZE RANGES Size Range U.S. Standard Millimeters Component Sieve Size Cobbles 75 3 inches 3" to No. 4 3" to 3/4" 3/4" to No. 4 No. 4 to No. 200 Gravel 75 to 4.75 Coarse Gravel 75 to 19 19 20 4.75 Fine Gravel Sand 4.75 to 0.073 No. 4 to No. 10 No. 10 to No. 40 Course 4.75 to 2 Medium 2 :0 0.425 Fine 0.425 to 0.075 No. 40 to No. 200 Fines (silt or clay) 0.075 No. 200



- 1. DUAL USCS SYMBOL, SUCH AS (SP-SM) DENOTES 5 TO 12% OF MINOR CONSTITUENT.
- SUBSURFACE INFORMATION FROM BORING AND IEST PIT LOGS DEPICT COMDITIONS ONLY AT THE SPECIFIC LOCATIONS AND DATES INDICATED. SOIL COMDITIONS AND MATER LEVELS AT OTHER LOCATIONS MAY DIFFER FROM CONDITIONS AT THESE LOCATIONS. ALSO THE CONDITIONS AT THESE LOCATIONS MAY CHANGE WITH TIME.
- BLOW COUNTS ON LOGS ARE THE NUMBER OF BLOWS TO DRIVE THE SAMPLER 6 INCHES WITH A 140 POUND HAMMER FALLING JO INCHES.
- GROUND WATER LEVEL
- HYDROCARBON LEVEL
- 6. HNU (ppm) ¹ RELATIVE CONCENTRATION OF ORGANIC VAPORS DETECTED IN HEADERS OVER SOIL SAMPLE WITH HNU MODEL PIOI PHOTOIONIZATION DETECTOR.

KEY TO SOIL SYMBOLS



BORING:B-1 PROJECT NAME: ARCO Harbor Island PROJECT NO. 512-223 RIG TYPE: Mobil B-23 LOCATION COORDINATES: N/A SCHEDULE WATER LEVEL SAMPLING METHOD: Split Spoon **INITIATED:** 7-30-87 DEPTH: 6.0' DRILLING CO: Kring Drilling 7-30-87 COMPLETED: 7-30-87 DATE:

TIME:

NA

BACKFILLED:

7-31-87

LOGGED BY: Douglas Hayes BORING DEPTH: 10.01 GROUND ELEVATION: NA SHEET 1 OF 1 SOIL TYPE SAMPLE DATA SOIL DESCRIPTION REMARKS Z SAMPLE SAMPLE SAMPLE DEPTH FEET SYMBOL BLOW USC 0 -SPT NA 5 10 SP SAND; Dark brown; fine to very fine; Trace free 5 sand primarily quartz; subrounded hydrocarbon on water to subangular; poorly graded; some table shell fragments; hydrocarbon saturated; wet 10 15-20-25-30



DRILLED BY: John Fisk

PROJECT NO. 512-223 PROJECT NAME: ARCO Harbor Island RIG TYPE: Mobil B-23 LOCATION COORDINATES: NA WATER LEVEL SCHEDULE SAMPLING METHOD: Split Spoon DEPTH: 6.0' INITIATED: 7-30-87 DRILLING CO: Kring Drilling DATE: 7-31-87 COMPLETED: 7-30-87 DRILLED BY: John Fisk TIME: NA BACKFILLED: 7-31-87 LOGGED BY: Douglas Haves BORING DEPTH: 10' SHEET 1 OF 1 GROUND ELEVATION: NA

GHU						1 00			
Z	SAMPLE DATA					TY	PE	SOIL DESCRIPTION	REMARKS
DEPTH FEET	SAMPLE	SAMPLE DEPTH	SAMPLE	BLOWS		nscs	SYMBOL		
5 - 10 - 20 - 25	NA	5	SPT	10	₹	SP		SAND; Dark brown; fine to very fine; sand primarily quartz; subrounded to subangular; poorly graded; some shell fragments; wet	
30	1								



PROJECT NAME: ARCO Harbor Island

LOCATION COORDINATES: NA

SCHEDULE

WATER LEVEL

SAMPLING METHOD: Split Spoon

DEPTH: 6.0'

COMPLETED: 7-29-87

DATE: 7-29-87

BACKFILLED: 7-30-87

TIME: NA

DUHILING. -

GRO	DUND ELEVATION: NA BORING DEPTH: 10.0' SHEET 1 OF 1				F 1							
z		s	AMPL	E DA	TA		SC	PE	SOIL DESCRIPTI	SOIL DESCRIPTION		
	SAMPLE	SAMPLE Depth	SAMPLE TYPE	BLOWS			nscs	SYMBOL				
-	NA	5	SPT	10		모	SP		SAND; Dark brown; fine to sand primarily quartz; su subangular; poorly graded shell fragments; hydrocar saturated; wet	brounded to	Trace fine hydrocarbon on water table	

LOGGED BY: Douglas Haves

BORING:B-4 PROJECT NO. 512-223 PROJECT NAME: ARCO Harbor Island LOCATION COORDINATES: NA RIG TYPE: Mobil B-23 WATER LEVEL SCHEDULE SAMPLING METHOD: Split Spoon **DEPTH:** 5.0' INITIATED: 7-30-87 DRILLING CO: Kring Drilling DATE: 7-30-87 COMPLETED: 7-30-87 DRILLED BY: John Fisk TIME: NA BACKFILLED: 7-31-87 LOGGED BY: Douglas Haves

UND	ELEV	ATION	: NA		В	ORING	3 DEP	TH: 10.0' SHEET 1 0	F1
	S	AMPL	E DA	TA		S O T Y	IL PE	SOIL DESCRIPTION	REMARKS
SAMPLE	SAMPLE DEPTH	SAMPLE	BLOWS			nscs	SYMBOL		
	5	SPT	12			SP		SAND; Dark brown; fine to very fine; sand primarily quartz; subrounded to subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet	Trace free hydrocarbon on water table
		SAMPLE NUMBER SAMPLE SAMPLE DEPTH &	SAMPLE NUMBER SAMPLE DEPTH SAMPLE TYPE	SAMPLE NUMBER SAMPLE DEPTH TYPE TYPE	SAMPLE DATA NOUMBER NOUMBER SAMPLE NOUMBER SAMPLE SAMPLE	SAMPLE DATA NOUMBER NOUMBER SAMPLE NOUMBER SAMPLE SAMPLE	SAMPLE DATA SOMPLE NUMBER NUMBER SAMPLE DATA SOMPLE D	SAMPLE DATA SOIL TYPE SAMPLE	SAMPLE DATA SOIL TYPE SOIL DESCRIPTION SOM BRANDIN BRANDIN SOIN BRA

PROJECT NAME: ARCO Harbor Island

LOCATION COORDINATES: NA

SCHEDULE

WATER LEVEL

WATER

INITIATED: 7-31-87

COMPLETED: 7-31-87

BACKFILLED: 7-31-87

GROUND ELEVATION: NA

DEPTH: 5.0'

DATE: 7-31-87

TIME: NA

BORING DEPTH: 10.0'

PROJECT NO. 512-223

RIG TYPE: Mobil B-23

SAMPLING METHOD: Split Spoon

DRILLING CO: Kring Drilling

DRILLED BY: John Fisk

LOGGED BY: Douglas Hayes

SHEET 1 OF 1

z		S	AMPL	E DA	TA		SC	IL PE	SOIL DESCRIPTION	REMARKS
DEPTH IN	SAMPLE	SAMPLE	SAMPLE	BLOWS			nscs	SYMBOL		
0 - - 5	NA	5	SPT	10		₽.	SP		SAND; Dark brown; fine to very fine; sand primarily quartz; subrounded to subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet	Trace free hydrocarbon on water table
10-										
15-						and the second	property.			
20-								,		
25-						-				
30-										

PROJECT NAME: ARCO Harbor Island

LOCATION COORDINATES: NA

SCHEDULE

WATER LEVEL

SAMPLING METHOD: Split Spoon

INITIATED: 7-30-87

COMPLETED: 7-30-87

DATE: 7-3-87

TIME: NA

BACKFILLED: 7-31-87


GRO	DUND	ELEV	ATIO	V: NA		В	ORIN	G DEF	TH: 10.0'	SHEET 1 O	F 1
z		s	AMPL	E DA	TA		SC	PE PE	SOIL DESCRIP	TION	REMARKS
O DEPTH I	SAMPLE	SAMPLE DEPTH	SAMPLE	BLOWS			nscs	SYMBOL			
5	NA	5	SPI	12		卢	SP		SAND; Dark brown; fine sand primarily quartz; subangular; poorly gradeshell fragments; hydrocsaturated; wet	subrounded to	Trace free hydrocarbon on water table
15-			*				200				
25-											

DRILLED BY: John Fisk

LOGGED BY: Douglas Haves

DUILLING. PROJECT NAME: ARCO Harbor Island PROJECT NO. 512-223 LOCATION COORDINATES: NA RIG TYPE: Mobil B-23 SCHEDULE WATER LEVEL SAMPLING METHOD: Split Speen INITIATED: 7-30-87 DEPTH: 5.0' DRILLING CO: Kring Drilling COMPLETED: 7-30-87 DATE: 7-30-87 DRILLED BY: John Fisk BACKFILLED: 7-31-87 TIME: NA LOGGED BY: Douglas Haves GROUND ELEVATION: NA BORING DEPTH: 10.01

			A1101	1, 312			ONIN	G DE	PTH: 10.0' SH	HEET 1 O	F1
z		S	AMPL	E DA	TA		SO	OIL PE	SOIL DESCRIPTIO		REMARKS
O DEPTH	SAMPLE	SAMPLE DEPTH	SAMPLE	BLOWS			nscs	SYMBOL			
10-	NA .	5	SPT	O)		모	SP		SAND; Dark brown; fine to v sand primarily quartz; subr subangular; poorly graded; carbon saturated; wet	very fine; rounded to hydro-	Trace free hydrocarbon on water table
1,											



PROJECT NAME: ARCO Harbor Island PROJECT NO. 512-223 LOCATION COORDINATES: NA RIG TYPE: Mobil B-23 SCHEDULE WATER LEVEL SAMPLING METHOD: Split Spoon INITIATED: 7-30-87 **DEPTH:** 5.0' DRILLING CO: Kring Drilling DATE: 7-30-87 COMPLETED: 7-30-87 DRILLED BY: John Fisk BACKFILLED: 7-31-87 l'IIME: NA LOGGED BY: Douglas Hayes GROUND ELEVATION: NA BORING DEPTH: 10.01

Z			AMPL		 	TY	PE	SOIL DESCRIPTION	REMARKS
DEPTH IN	SAMPLE	SAMPLE	SAMPLE	вгомѕ		nscs	SYMBOL		*
5 -	NA	5	SPI	7	₽-	SP		SAND; Dark brown; fine to very fine; sand primarily quartz; subrounded to subangular; poorly graded; some shell fragments; wet	
15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					ingularite Valence (· · · · · · · · · · · · · · · · · · ·	•		
5-									



BORING:B-9 PROJECT NO. 512-223 PROJECT NAME: ARCO Harbor Island RIG TYPE: Mobil B-23 L'OCATION COORDINATES: NA SCHEDULE WATER LEVEL SAMPLING METHOD: Split Speen INITIATED: 7-30-87 DEPTH: 5.0' DRILLING CO: Kring Drilling DATE: 7-30-87 COMPLETED: 7-30-87 DRILLED BY: John Fisk BACKFILLED: 7-31-87 TIME: NA LOGGED BY: Douglas Hayes

ROUND	ELEV	ATION	: NA		В		DEP	TH: 10.0' s	HEET 1 OF 1	
<u>z</u>	s	AMPL	E DAT	A		SO TY	IL PE	SOIL DESCRIPTION	DN	REMARKS
DEPTH FEET SAMPLE NUMBER	SAMPLE	SAMPLE TYPE	BLOWS			nscs	SYMBOL			
5 - NA	5	SPT	7	-	₹.	SP		SAND; Dark brown; fine to fine; sand primarily quart subrounded to subangular; graded; some shell fragment	very tz; poorly nts; wet	
20-										

PROJECT NAME: ARCO Harbor Island PROJECT NO.512-223 LOCATION COORDINATES: RIG TYPE: Mobil B-23 SCHEDULE WATER LEVEL SAMPLING METHOD: Split Spoon INITIATED: 7-31-87 **DEPTH: 5.0'** DRILLING CO: Kring Drilling COMPLETED: 7-31-87 7-31-87 DATE: DRILLED BY: John Fisk BACKFILLED: 7-31-87 TIME: NA LOGGED BY: Douglas Haves GROUND ELEVATION: NA BORING DEPTH: 10.0' SHEET 1 OF SAMPLE DATA SOIL SOIL DESCRIPTION Z TYPE REMARKS SAMPLE DEPTH FEET SAMPLE SAMPLE DEPTH S USCS SYMBOI BLOW 0 프 NA 5 -5 SPT SP SAND; Dark brown; fine to very fine; Irace free sand primarily quartz; subrounded to hydrocarbon on water subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet 10-. 1 15 20-25 30 ENGINEERING ENTERPRISES, INC.

DUMING:D'II PROJECT NAME: ARCO Harbor Island PROJECT NO. 512-223 LOCATION COORDINATES: NA RIG TYPE: Mobil B-23 SCHEDULE WATER LEVEL SAMPLING METHOD: Split Spoon INITIATED: 7-31-87 **DEPTH:** 5.0' DRILLING CO: Kring Drilling COMPLETED: 7-31-87 DATE: 7-31-87 DRILLED BY: John Fisk BACKFILLED: 7-31-87 TIME: NA LOGGED BY: Douglas Hayes GROUND ELEVATION: NA BORING DEPTH: 10.0' SHEET 1 OF 1

z			AMPL	E DA	TA		SC	PE PE	SOIL DESCRIPTION	REMARKS
O DEPTH I	SAMPLE	SAMPLE	SAMPLE	BLOWS	HNU(ppm)		nscs	SYMBOL		
5 -	NA	5	SPT	. •		□	SP		SAND; Dark brown; fine to very fine; sand primarily quartz; subrounded to subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet	Trace free hydrocarbon on water table
5-							To a comment of			
5-										



BORING:B-12 PROJECT NAME: ARCO Harbor Island PROJECT NO. 512-223 LOCATION COORDINATES: NA RIG TYPE: Mobil B-23 SCHEDULE -WATER LEVEL SAMPLING METHOD: Split Spoon INITIATED: 7-31-87 **DEPTH: 5.0'** DRILLING CO: Kring Drilling COMPLETED: 7-31-87 DATE: 7-31-87 DRILLED 5 /: John Fisk BACKFILLED: 7-31-87 TIME: NA LOGGED BY: Douglas Hayes

BROUND	ELEV	ATION	۷:		В	ORIN		TH: SHEET	OF 1
<u>z</u>	S	AMPL	E DA	TA		SC	PE	SOIL DESCRIPTION	REMARKS
PEPTH FEET SAMPLE NUMBER	SAMPLE	SAMPLE	BLOWS	HNU(ppm)		nscs	SYMBOL		
6 — NA 10 —	5	SPT			모	SP		SAND; Dark brown; fine to very firsand primarily quartz; subrounded subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet	ne; Trace free to hydrocarbon on water table
25-									

PROJECT NAME: ARCO Harbor Island

LOCATION COORDINATES:

SCHEDULE

WATER LEVEL

INITIATED: 7-31-87

שנוחות ביים

DEPTH: 5.0'

COMPLETED: 7-31-87

DATE: 7-31-87

BACKFILLED: 7-31-87

NA TIME:

GROUND ELEVATION:

BORING DEPTH: 10.01

PROJECT NO. 512-223

RIG TYPE: Mobil B-23

SAMPLING METHOD: Split Spoon

DRILLING CO: Kring Drilling

DRILLED BY: John Fisk

LOGGED BY: Douglas Hayes

SHEET 1 OF 1

7		s	AMPL	E DA	ΓΑ .		S O T Y	IL PE	SOIL DESCRIPTION	REMARKS
PEET FEET	SAMPLE	SAMPLE DEPTH	SAMPLE TYPE	BLOWS	HNU(ppm)		nscs	SYMBOL		
5	NΑ	5	SPT	7		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	SP		SAND; Dark brown; fine to very fine; sand primarily quartz; subrounded to subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet	Trace free hydrocarbon on water table
15-						garant.	, comment			
20-										
25-	-									
30-	-									

BORING:B-14 PROJECT NAME: ARCO Harbor Island PROJECT NO. 512-223 LOCATION COORDINATES: NA RIG TYPE: Mobil B-23 SCHEDULE WATER LEVEL SAMPLING METHOD: Split Spoon INITIATED: 7-31-87 5.0' DEPTH: DRILLING CO: Kring Drilling COMPLETED: 7-31-87 DATE: 7-31-87 DRILLED BY: John Fisk BACKFILLED: 7-31-87 TIME: NA LOGGED BY: Douglas Hayes

NA 5 SPT 12 SP SAND; Dark brown; fine to very fine; trace free	_		S	AMPL	E DA	TA	- >	SC	PE	SOIL DESCRIPTION	REMARKS
SP SAND; Dark brown; fine to very fine; sand primarily quartz; subrounded to subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet	FEET	SAMPLE	SAMPLE	SAMPLE	BLOWS	HNU(ppm)	×				
	5 - 1	NA	5	SPT	12		모			<pre>sand primarily quartz; subrounded to subangular; poorly graded; som shell fragments; hydrocarbon</pre>	hydrocarbon on water
	1 1 1										
25-	-										



DUNING.D" IV

PROJECT NAME: ARCO Harbor Island

LOCATION COORDINATES: NA

SCHEDULE

WATER LEVEL

INITIATED: 7-31-87

GROUND ELEVATION: NA

COMPLETED: 7-31-87

BACKFILLED: 7-31-87

DATE: 7-31-87

TIME: NA

DEPTH: 5.0'

BORING DEPTH: 10.0'

PROJECT NO. 512-223

RIG TYPE: Mobil B-23

SAMPLING METHOD: Split Spoon

DRILLING CO: Kring Drilling

DRILLED BY: John Fisk


LOGGED BY: Douglas Hayes

SHEET 1 OF 1

			X1101) I L	TISHEET 1 O	
z		S	AMPL	E DA	TA		TY	PE	SOIL DESCRIPTION	REMARKS
O DEPTH I	SAMPLE	SAMPLE DEPTH	SAMPLE	BLOWS	HNU(ppm)		nscs	SYMBOL		
5 —	NA .	5	SPT	11		∇-	SP		SAND; Dark brown; fine to very fine; sand primarily quartz; sunrounded to subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet	trace free hydrocarbon on water table
16-							a series e de la companya de la comp			
25-										



WELL:MW-1 **BORING:** PROJECT NO. 512-223 PROJECT NAME: ARCO Harbor Island Mobil B-23 LOCATION/COORDINATES: NA RIG TYPE: WATER LEVEL SCHEDULE SAMPLING METHOD: Split Spoon 7-29-87 6.0' INITIATED: DEPTH: DRILLING CO: Kring Drilling 7-29-87 COMPLETED: 7-29-87 DATE: DRILLED BY: John Fisk BACKFILLED: 7-30-87 TIME: NA 9.11 LOGGED BY: Douglas Hayes GROUND ELEVATION: CASING ELEVATION:





WELL:MINA-

ROKING:

PROJECT NAME: ARCO Harbor Island

LOCATION/COORDINATES : NA

SCHEDULE

INITIATED: 7-29-87

COMPLETED: 7-29-87

BACKFILLED: 7-30-87

CASING ELEVATION: 8.80

WELL DEPTH: 14.0'

WATER LEVEL

DEPTH: 6.0'

DATE: 7-29-87

TIME: NA

GROUND ELEVATION: 9.54

BORING DEPTH: 15.0'

PROJECT NO. 512-223

RIG TYPE: Mobil B-23


SAMPLING METHOD: Split Spoon

DRILLING CO: Kring Drilling

DRILLED BY: John Fisk


LOGGED BY: Douglas Hayes

SHEET 1 OF 1






WELL:MW-3 **BORING:** PROJECT NO. 512-223 ARCO Harbor Island PROJECT NAME : LOCATION/COORDINATES : NA RIG TYPE: Mobil B-23 SCHEDULE WATER LEVEL SAMPLING METHOD: Split Spoon DEPTH: 5.0' 7-30-87 INITIATED: DATE: 7-30-87 DRILLING CO: Kring Drilling COMPLETED: 7-30-87 DRILLED BY: John Fisk BACKFILLED: 7-31-87 TIME: NA **GROUND ELEVATION:** 9.35 CASING ELEVATION: 11.45 LOGGED BY:Douglas Hayes






WELL:MW-4 **BORING:** PROJECT NAME : ARCO Harbor Island PROJECT NO. 512-223 LOCATION/COORDINATES : NA RIG TYPE: Mobil B-23 SCHEDULE WATER LEVEL SAMPLING METHOD: Split Spoon 7-30-87 INITIATED: **DEPTH:** 5.0' COMPLETED: 7-30-87 DATE: 7-30-87 DRILLING CO: Kring Drilling BACKFILLED: 7-31-8 TIME: NA DRILLED BY: John Fisk 10.94 CASING ELEVATION: GROUND ELEVATION: LOGGED BY: Douglas Haves WELL DEPTH: 13.0' BORING DEPTH: SHEET 1 OF 1






WELL:MW-5 **BORING:** PROJECT NAME : ARCO Harbor Island PROJECT NO. 512-223 LOCATION/COORDINATES : RIG TYPE: Mobil B-23 SCHEDULE WATER LEVEL SAMPLING METHOD: Split Spoon 7-31-87 INITIATED: 5.01 DEPTH: COMPLETED: 7-31-87 DRILLING CO: Kring Drilling DATE: 7-31-87 BACKFILLED: 7-31-87 TIME DRILLED BY: John Fisk CASING ELEVATION: NA GROUND ELEVATION:





LOGGED BY: Douglas Hayes

WELL:R-1 **BORING:** PROJECT NAME: ARCO Harbor Island PROJECT NO. 512-223 LOCATION/COORDINATES : NA RIG TYPE: Nobil B-23 SCHEDULE WATER LEVEL SAMPLING METHOD: Auger cuttings INITIATED: 7-27-87 **DEPTH:** 9.0' COMPLETED: 7-27-87 7-27-87 DATE: DRILLING CO: Kring Drilling BACKFILLED: 7-31-87 TIME: NA John Fisk DRILLED BY: CASING ELEVATION: 12.56 **GROUND ELEVATION:** 13.29 LOGGED BY: Douglas Hayes





WELL:R-2

BORING:

PROJECT NAME : ARCO Harbor Island

LOCATION/COORDINATES : NA

SCHEDULE

INITIATED:

7-28-87

COMPLETED: 7-28-87

BACKFILLED: 7-31-87

CASING ELEVATION: 12.56

WELL DEPTH: 19.0'

WATER LEVEL

DEPTH: 9.0'

DATE: 7-28-87

TIME: NA

GROUND ELEVATION: 13.35

BORING DEPTH: 20.0'

PROJECT NO. 512-223

RIG TYPE: Mobil B-23

SAMPLING METHOD: Auger cuttings

DRILLING CO: Kring Drilling

DRILLED BY: John Fisk

LOGGED BY: Douglas Haves

SHEET 1 OF 1

SOUND BY A WAY OF THIS Mounted Well Protector Casing SAND; Dark brown; fine to very finers and primarily quartz; subrounded to subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet 10- 2" Diameter PVC Screen U.020 Slot Size 16- 10/20 Colorado Silica PVC END CAP 20- 20- 20- 20- 20- 20- 20- 20	z	WELL CONSTRUCTION	SC	PE	SOIL DESCRIPTION		BAMPL	E DA	ra .	
Flush Mounted Well Protector Cement Grout 2 Diameter PVC Gasing SAND; Dark brown; fine to very fine; sand primarily quartz; subrounded to subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet 2" Diameter PVC Screen 0.020 Slot Size 10/20 Colorado Silica PVC END CAP	DEPTH IN FEET	PUC END CAP	uscs	SYMBOL			SAMPLE	SAMPLE	SAMPLE	BLOWS
Cement Grout 2' Diameter PVC Casing SAND; Dark brown; fine to very fine- sand primarily quartz; subrounded to subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet 2" Diameter PVC Screen U.020 Slot Size 10/20 Colorado Silica PVC END CAP	°	Flush Mounted Well								
	10-	Cement Grout 2' Diameter PVC Casing Bentonite 2" Diameter PVC Screen 0.020 Slot Size -10/20 Colorado Silica			sand primarily quartz; subrounded to subangular; poorly graded; some shell fragments; hydrocarbon saturated; wet					
	25-									

WELL:R-3 **BORING:** PROJECT NAME : ARCO Harbor Island 512-223 PROJECT NO. LOCATION/COORDINATES : RIG TYPE: Mobil B-23 SCHEDULE WATER LEVEL SAMPLING METHOD: Auger Cuttings INITIATED: 7-29-87 9.01 DEPTH: COMPLETED: 7-29-87 7-29-87 DRILLING CO: Kring Drilling DATE: SACKFILLED: 7-31-87 TIME: NA DRILLED BY: John Fisk CASING ELEVATION: 13.00 GROUND ELEVATION: LOGGED BY: Douglas Hayes WELL DEPTH: BORING DEPTH: 20.0' SHEET 1 OF 1

